

MUNICIPAL CORPORATION JALANDHAR

TOTAL LIST OF PARKS IN JALANDHAR CITY

XEN SH. KASHMIRI LAL :- 9872989192

L.S.O. SH. DALJIT SINGH :- 8568841515

J.E. SH. ONKAR NATH :- 9501795308

SURVEY YEAR - 2017

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardner	Status Of The Gardner (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
1	Bank Colony Slumpur Road Opp New Guru Amar Dass Nagar	1	2 Games, 1 Room	242'X72'	1	M.C.J	M.C.J	Under Developed	Only Boundary Wall/ No Grill/Repair Boundary Wall / Paint
2	Opp.173B, Shaheed Bhagat Singh Nagar	2	4 Benches 7 Games	80'X67'	1	Through Matching Grant	Shaheed Bhagat Singh Nagar Housing Society	Under Developed	Boundary Wall , Grill Required Paint/ Games Are Broken
3	113, Shaheed Bhagat Singh Nagar Near Railway Line	2	2 Benches, 1 Game	100'X79'X15'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint/ No Games/ Gate Is Broken
4	Shaheed Bhagat Singh Nagar Opp Maqsudan Bypass	2	No Facilities	380'X50'X20'	1	Through Matching Grant	Shaheed Bhagat Singh Nagar Housing Society	Developed	No Boundary Wall Required Boundary Wall & Benches
5	Shaheed Bhagat Singh Nagar Opp 159. Zone Wali Park	2	1 Tubewell, 2 Benches, 2 Games, 1 Zone	228'X43'	Nil	M.C.J	M.C.J	No Developed	All Things Are Broken
6	Shaheed Bhagat Singh Nagar Opp 302 Baba Balak Nath Park	2	2 Games, 12 Benches	180'X112'	1	Through Matching Grant	Shaheed Bhagat Singh Housing Society	Developed	Repair Boundary Wall / Paint/ No Light/ Required 1 Hut
7	Seth Hukam Chand Colony Opp House No. 207 Backside C.T Public School	2	8 Benches, 1 Tubewell, 1 Fountain, 1 Store,	93'X61'	1	Through Matching Grant	Seth Hukam Chand Colony Welfare Society	Developed	Excellent
8	Seth Hukam Chand Colony Opp House No. 34	2	10 Benches, 1 Community Hall, 1 Hut, 1 Tubewell, 5	211'X121'	1	Through Matching Grant	Seth Hukam Chand Colony Welfare Society	Developed	Repair Boundary Wall / Paint
9	Super Green Park Opp House No. 121	2	6 Benches, 5 Games	150'X1030'	1	Through Matching Grant	Super Green Park Welfare Society	Developed	Repair Boundary Wall / Paint
10	Guru Amar Dass Nagar Opp House No.9 (Gandhi Park)	2	5 Benches, 1 Game	102'X96'	1	M.C.J	M.C.J	Developed	No Footpath, No Light, Repair Boundary Wall / Paint
11	Guru Amar Dass Nagar Opp House No.126	2	2 Games	78'X40'	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall & Grill , No Light / Paint
12	Guru Amar Dass Nagar Opp House No.158-159	2	1 Hut, 5 Games, 9 Benches	190'X97'	1	Through Matching Grant	Green Park Guru Amar Dass Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
13	Guru Amar Dass Nagar Near Ganda Nala & House No. 54	2	6 Games, 5 Benches, 1 Room, 1 Suvidha	400'X333'	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall & Grill
14	Guru Amar Dass Nagar Near House No. 190-190 A Near Ganda Nala	2	1 Hut, 16 Benches, 5 Games	380'X110'	1	Through Matching Grant	The Janta Welfare Society	Developed	Repair Boundary Wall / Paint
15	Guru Amar Dass Nagar Near House No. 361/362	2	No Facilities	105'X30'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
16	Guru Amar Dass Nagar Opp M.I.G Flat Near Ganda Nala	2	No Facilities	75'X45'	Nil	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
17	Guru Amar Dass Nagar Near House No. 474	2	3 Games	150'X160'X90'	Nil	M.C.J	M.C.J	No Developed	No Footpath, No Benches, No Light
18	Guru Amar Dass Nagar Opp House No.51	2	5 Games, 8 Benches	165'X105'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint/ No Light
19	Transport Nagar Opp Saipur	2	1 Tubewell	310'X30'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
20	Transport Nagar Opp Petrol Pump.	2	No Facilities	250'X50'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
21	Kalia Colony Phase 2 Near Ganda Nala	2	3 Games	150'X40'	1	Through Matching Grant	Kalia Colony Development & Social Society	No Developed	Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
22	Guru Amar Dass Nagar Opp M.I.G Flat Near Kalia Colony	2	6 Benches	105'X88'	2	Through Matching Grant	M.C.J	Developed	Repair Boundary Wall / Paint/ Two Side No Grill
23	Shaheed Bhagat Singh Nagar Opp House No. 6 & Market	2	2 Benches, 1 Game	75'X75'	1	Through Matching Grant	Shaheed Bhagat Singh Housing Society	Developed	Repair Boundary Wall / Paint
24	Shaheed Bhagat Singh Nagar Opp House No.107	2	2 Benches, 2 Games	125'X80'X8'	1	Through Matching Grant	Shaheed Bhagat Singh Housing Society	Developed	Repair Boundary Wall / Paint
25	Shaheed Bhagat Singh Nagar Opp House No.235 & Arya Samaj Mandir	2	4 Benches, 1 Shiv Mandir, 1 Hut, 2 Games	100'X33'	Nil	Maintained By	Mohalla	Developed	No Light /Repair Boundary Wall / Paint
26	Shaheed Bhagat Singh Nagar Opp House No.487	2	2 Games, 2 Benches, 1 Tubewell	115'X58'	Nil	M.C.J	M.C.J	No Developed	Games & Grill Are Broken
27	Aman Nagar Opp 104.	4	1 Bench, 1 Tubewell, 1 Fountain	275'X66'X75'	1	Through Matching Grant	Aman Nagar Youth Welfare Society	Developed	No Light/Repair Boundary Wall / Paint
28	Preet Nagar Sodal Road .	4	2 Benches	28'X29'X17'	2	Through Matching Grant	Aman Nagar Preet Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
29	Kishanpura Baba Balak Nath Mandir Park	5	Only Lights	102'X100'	1	Through Mandir	Mandir Parbandhk Committee	Developed	Repair Boundary Wall / Paint
30	Kishanpura Baba Balak Nath Mandir Park	5	Only Lights	250'X200'	-	Mandir Parbandhk Committee	Mandir Parbandhk Committee	Developed	Good
31	New Vikaspuri Opp House No. 1-A	5	1 Hut, 3 Benches, 4 Games	160'X130'	2	Through Matching Grant	Vikasppuri Welfare Society	Developed	Repair Boundary Wall / Paint
32	Lakshmpura Maharaja Agarseen Park	5	13 Benches, 3 Games, 1 Hut, 1 Tubewell	147'X114'	1	Through Matching Grant	Lakshmpura Welfare Society	Developed	Repair Boundary Wall / Paint
33	Kishanpura Shamshan Ghat Park	5	10 Benches, 1 Fountain	150'X90'X70'	2	Through Matching Grant	Samarpan Welfare Society	Developed	No Boundary Wall
34	Kishanpura House Opp No. N.A-176	7	1 Tubewell, 12 Benches	126'X72'	1	M.C.J	M.C.J	No Developed	No Footpath/ Repair Boundary Wall / Paint
35	Prithvi Nagar Opp House No. 52	7	1 Hut, 4 Benches, 1 Tubewell	130'X113'	-	M.C.J	M.C.J	No Developed	Broken Gate & Grill / No Light & Water
36	Karol Bagh Opp Dips School	9	1 Tubewell, 2 Benches	145'X80'	Nil	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
37	Karol Bagh Opp House No. 505-A	9	8 Benches, 1 Hut	150'X125'	1	Through Matching Grant	Kot Ram Dass Welfare Society	Under Developed	Repair Boundary Wall / Paint
38	Rail Vihar Opp House No. 114	9	1 Tubewell, 1 Game, 4 Benches	300'X150'	1	Through Matching Grant	Kot Ram Dass Welfare Society	Under Developed	Repair Boundary Wall / Paint
39	Kot Ram Dass Nagar Shamshan Ghat	9	3 Benches	140'X70'	1	Through Matching Grant	Kot Ram Dass Welfare Society	Developed	Required Benches
40	Rail Vihar Opp House No. 123	9	1 Game, 4 Benches	188'X125'	Nil	M.C.J	M.C.J	Under Developed	No Boundary Wall/ No Light
41	Karol Bagh (Gulmarg Park) Opp House No. 9	9	2 Benches	120'X70'	Nil	M.C.J	M.C.J	Under Developed	Boundary Wall Need To Paint
42	Professor Colony ,Park No.1,Opp. House No.68	10	1 Community Hall,8 Benches,	140'X100'	1	Through Matching Grant	Professor Colony Welfare Society	Developed	Repair Boundary Wall/ Paint
43	Professor Colony ,Park No.3,Opp. House No.114	10	Tubewell, 7 Benches	104'X60'	1	Through Matching Grant	Professor Colony Welfare Society	Developed	Repair Boundary Wall/ Paint
44	Profesor Colony,Park No.2 Opp House No. 21	10	2 Benches	86'X76'	1	Through Matching Grant	Professor Colony Welfare Society	No Developed	Repair Boundary Wall/ Paint
45	Ladhewali, Near Gurudwara Saheb, Dr. Ambedkar Park	10	No Faciiltes	173'X25'	Nil	Through Matching Grant	Social Welfare Society Ladhewali	No Developed	Repair Boundary Wall/ Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
46	Ladhewali, Opp Government Sen. Sec School,	10	1 Hut	135'X66'	1	Through Matching Grant	Social Welfare Society Ladhewali	No Developed	Repair Boundary Wall/ Paint
47	Ladhewali, Below High Power Wire	10	9 Benches	100'X150'	2	Mohalla Society	Maintained By Mohalla Society	No Developed	Boundary Wall Required
48	Ladhewali Near Counsellor Resident	10	6 Benches, Library And A House	247'X107'	1	Through Matching Grant	Social Welfare Society Ladhewali	No Developed	Repair Boundary Wall/ Paint
49	Datar Nagar Opp House No. 30	10	3 Games, 8 Benches	225'X150'	1	Through Matching Grant	Datar Nagar Welfare Society	Under Developed	No Boundary Wall/ No Footpath
50	Atwal Colony Cantt Road	10	1 Tubewell	120'X70'	1	M.C.J	M.C.J	Under Developed	No Boundary Wall
51	New Dashmesh Nagar Ext., Gas Pipe Line Is Underlying	11	4 Benches	320'X73X51	1	Through Matching Grant	Development Committee Dhanowali	Under Developed	Boundary Wall Is Broken
52	Dhillwan Colony, Diamond City, Near Tanki, Opp House No. 67	11	No Games	104'X80'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall
53	Dhillwan Colony, Diamond City, Red Park 1	11	No Facilities	83'X55'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall
54	Dhillwan Colony, Diamond City, Park 2	11	No Facilities	90'X50'	1	Through Matching Grant	Development Committee Dhanowali	Under Developed	Repair Boundary Wall
55	Pind Nangal Shama, Near Gurdwara Singh Sabha,	11	No Facilities	145'X85'	1	Through Matching Grant	Development Committee Dhanowali	Under Developed	Repair Boundary Wall
56	Sunny Enclave, House No. 47B, Near Shiv Shakti Mandir	11	No Facilities	85'X30'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall
57	Sunny Enclave, Near Shiv Shakti Mandir	11	1 Hut	85'X63'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall
58	Dhillawan, Opp House No. 44	11	1 Room	200'X125'	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall
59	Dhillwan, Near Railway Line, Opp Primary School	11	20 Benches	151'X125'	1	Through Matching Grant	Development Committee Dhanowali	Developed	Repair Boundary Wall
60	Arman Nagar Park, Opp House No. 68,	11	No Facilities	98'X64'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall
61	Arman Nagar ,Sunny Prime, Opp House No. 42,	11	No Facilities	130'X25'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall
62	Sunny Enclave, Opp House No. 47-B Near Mandir	11	No Facilities	47'X85'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall/ No Plants
63	New Defence Colony, Ph2, Opp House No. 136	12	1 Community Hall, 6 Benches	167'X67'X40'	1	Through Matching Grant	Defence Colony Phase 2 Welfare Association	Developed	Repair Boundary Wall/ Paint
64	New Defence Colony, Ph1, Park No. 1 Opp House No. 63	12	5 Beches	100'X80'	1	Through Matching Grant	New Defence Colony Welfare Society	Developed	Repair Boundary Wall/ Paint
65	New Defence Colony, Park 2, Opp House No. 163	12	6 Benches	120'X80'	1	Through Matching Grant	New Defence Colony Welfare Society	Developed	Repair Boundary Wall/ Paint
66	Birring, Opp House No. 690, Joginder Singh Park	12	3 Benches	106'X40'	2	Through Matching Grant	Development Committee Birring	Under Developed	Repair Boundary Wall/ Paint
67	New Defence Colony Phase 1 Opp House No. 644	12	4 Benches	120'X80'	1	Through Matching Grant	New Defence Colony Welfare Association	Developed	Repair Boundary Wall / Paint
68	Birring Animal Hospital Wali Park	12	1 Sport Club, 1 Animal Hospital, 1 Hut, 3 Benches, 1	180'X43'	1	Through Matching Grant	Development Committee Birring	Developed	Repair Boundary Wall / Paint/ No Light
69	New Defence Colony Phase 1 Opp House No. 575	12	1 Hut, 1 Tubewell	135'X82'	1	Through Matching Grant	New Defence Colony Association	Developed	Only Boundary Wall Without Grill/ Required Benches

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
70	Dashmesh Nagar, Opp House No. 16	13	1 Hut, 10 Benches, 4 Games	161'X60'	1	Through Matching Grant	Kakki Pind Welfare Society	Developed	No Light, No Dustbin
71	Dashmesh Nagar, Children Park, Park No. 2, Opp House No. 58	13	Tubewell	185'X30'	2	Through Matching Grant	Kakki Pind Welfare Society	Under Developed	No Boundary Wall/ No Plants
72	Dakoha, Opp Shamshan Ghat,	13	No Facilities	146'X13'	2	Through Matching Grant	Kakki Pind Welfare Society	Under Developed	No Games / Repair Boundary Wall/ Paint
73	Baba Budha Ji Enclave, Opp House No. 11	13	Tubewell, 5 Benches	100'X65'	2	Through Matching Grant	Kakki Pind Welfare Society	Under Developed	Boundary Wall Is Broken
74	National Avenue, Opp House No. 102/10	13	1 Tubewell,	86'X38'	1	Through Matching Grant	Kakki Pind Welfare Society	Under Developed	No Plants/ No Grass/ Under Progress Of Contractor
75	Shri Ravidass Colony Opp Near Rama Mandi Flyover	13	1 Tubewell, 2 Games, 2 Benches	250'X58'	1	Through Matching Grant	Kakki Pind Welfare Society	Under Developed	Repair Games & All Things Are Required Here.
76	Kirti Nagar Opp Ladowali Road.	14	5 Games, 1 Hut, 11 Benches, 1 Tubewell	75'X65'	1	Through Matching Grant	Kirti Nagar Link Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
77	Kirti Nagar Opp House No. 41 & 31-32.	14	6 Benches, 2 Games, 1 Tubewell	85'X55'	1	Through Matching Grant	Kirti Nagar Link Nagar Welfare Society	Under Developed	Repair Light, Bondary Wall, Footpath, Room & Paint
78	Kirti Nagar Opp House No. 55	14	1 Tubewell, 5 Benches, 2 Games, 1 Water	55'X45'	1	Through Matching Grant	Kirti Nagar Link Nagar Welfare Society	Under Developed	Required To Repair All Things
79	Partap Road Near Railway Station	16	No Facilities	84'X35'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint/ No Light No Games
80	Partap Road Opp House No. 37	16	8 Benches, 1 Hut	138'X70'X40'	1	Through Matching Grant	Partap Road Welfare Society	Developed	Repair Boundary Wall / Paint
81	Mohalla New Gobind Garh Opp House No. 9-A	16	2 Benches, 1 Tubewell	90'X38'40'	1	Through Matching Grant	Mohalla Gobind Garh Welfare Society	Under Developed	Repair Boundary Wall / Paint
82	Bhim Nagar, Near Domoria Pul, Dr. Ambedkar Park, Qazi Mandi	17	No Facilities	300'X150'	1	Through Matching Grant	Daulatpuri Welfare Society	Developed	Repair Boundary Wall / Paint
83	Guru Gobind Singh Avenue Main Maket Opp House No.739	17	1 Bathroom	66'X51'	Nil	M.C.J	M.C.J	No Developed	All Things Are Required Here.
84	Guru Gobind Singh Avenue Mother Teresa Park	17	No Facilities	67'X65'X32	Nil	Through Matching Grant	Daulatpuri Welfare Society	Developed	Repair Boundary Wall / Paint
85	Guru Gobind Singh Avenue Maa Bharati Park.	17	7 Benches, 1 Hut, 1 Tubewell	268'X74'X70'	2	Through Matching Grant	Maa Bharati Sewa Sang	Under Developed	Repair Boundary Wall / Paint/ No Lights/ Broken Footpath
86	Guru Gobind Singh Avenue Shiv Park.	17	1 Hut, 6 Benches, 1 Game	162'X92'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
87	Guru Gobind Singh Avenue Opp House No. 560	17	1 Hut, 2 Games	132'X55'	1	Through Matching Grant	Daulatpuri Welfare Society	Developed	Repair Boundary Wall / Paint
88	Guru Gobind Singh Avenue Near Sarbh Hitkari Keshav Mandir	17	5 Benches, 1 Hut	151'X47'	1	Through Matching Grant	Sarab Hitkari Shikasha Samiti Chandigarh	Developed	Repair Boundary Wall / Paint
89	Guru Gobind Singh Avenue Trinty College Backside Street	17	1 Hut	119'X130'	1	Through Matching Grant	Daulatpuri Welfare Society	Under Developed	Repair Boundary Wall / Paint
90	Guru Gobind Singh Avenue Backside Trinty College Wall	17	No Facilities	117'X110'X40'	Nil	M.C.J	M.C.J	No Developed	Available Only Boundy Wall
91	Near Sarbh Hitkari Primary School Opp House. 731	17	No Facilities	146'X49'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
92	Guru Gobind Singh Avenue Opp H.I.G/M.I.G Appartment	17	1 Room For Securty Guard	136'X58'X45'	1	Through Matching Grant	Daulatpuri Welfare Society	Under Developed	Repair Boundary Wall / Paint
93	Guru Gobind Singh Avenue H.I.G/M.I.G Appartment	17	No Facilites	279'X110'X58'	1	Through Matching Grant	Daulatpuri Welfare Society	Developed	Good

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardner	Status Of The Gardner (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
94	Guru Gobind Singh Avenue Axaradam Road	17	No Facilites	119'X22'	Nil	M.C.J	M.C.J	No Developed	All Things Are Required Here.
95	Guru Gobind Singh Avenue Axaradam Road.	17	No Facilites	60'X23'	Nil	M.C.J	M.C.J	No Developed	All Things Are Required Here.
96	Guru Gobind Singh Avenue Opp House No. 221	17	1 Hut	93'X62'	1	M.C.J	M.C.J	Under Developed	No Lights/ Repair Boundary Wall / Paint
97	Guru Gobind Singh Avenue Opp House No. 220	17	1 Tubewell	128'X60'	Nil	M.C.J	M.C.J	No Developed	All Things Are Required Here.
98	Guru Gobind Singh Avenue Opp H.I.G Flat No. 9	17	1 Hut, 2 Bencehs	129'X111'X40'	1	Through Matching Grant	Daulatpuri Welfare Society	Under Developed	Repair Boundary Wall / Paint
99	Guru Gobind Singh Avenue Kids Opp House No. 25	17	6 Games	171'X162'X20'	1	Through Matching Grant	Daulatpuri Welfare Society	Under Developed	Repair Boundary Wall / Paint
100	Guru Gobind Singh Avenue Opp Kothi 10 Marla, & House No. 94	17	9 Games	300'X173'	1	Through Matching Grant	Daulatpuri Welfare Society	Developed	Maharaja Agarseen Statue Hand Is Broken & Required Paint.
101	Guru Gobind Singh Avenue Flat Opp House No.86 To 90	17	No Facilites	231'X39'X11'	Nil	M.C.J	M.C.J	No Developed	No Lights/ Repair Boundary Wall / Paint
102	Guru Gobind Singh Avenue H.I.G Flat Opp House No.68	17	1 Hut	117'X86'X35'	1	Through Matching Grant	Daulatpuri Welfare Society	Developed	Repair Boundary Wall / Paint
103	Guru Gobind Singh Avenue Opp House No.206 (Sharma House)	17	1 Hut, 4 Games, 9 Benches	213'X92'	1	Through Matching Grant	Guru Gobind Singh Avenue Administrative	Developed	Good
104	Nehru Gardan Park.	18	11 Iron Benches, 32 Cement Concrete Benches.	540'X480'	6	Through Contractor	A.S Enterprises Hoshiarpur	Developed	Boundary Wall & Grill Required To Paint
105	Phagwara Gate Dispensary Wali Park	18	No Facilites	85'X30'X28'	Nil	M.C.J	M.C.J	No Developed	Boundary Wall & Grill Are Broken, No Grass & Plants
106	Partap Bagh Opp Mandir	18	1 Tubewell	84'X66'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint/ No Grill
107	Bhai Ditt Singh Nagar Opp House No. 131 Near Jaswant Nagar.	19	6 Games, 7 Benches, 1 Hut, 1 Tubewell	132'X96'	1	Through Matching Grant	Bhai Ditt Singh Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint/ Grill Are Broken
108	Bhai Ditt Singh Nagar Opp House No. 44 Inside A Pond	19	No Facilities	250'X80'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
109	Bhai Ditt Singh Nagar Opp House No. 24 (Dhusshra Ground)	19	1 Room	225'X100'X75'	2	Through Matching Grant	Shri Ram Welfare Society Dhusshra Committee	No Developed	Repair Boundary Wall / Paint/ Gate Are Broken
110	Bhai Ditt Singh Nagar Opp House No. E.D 93	19	2 Games, 4 Benches	102'X48'	1	Through Matching Grant	Bhag Karam Bakash Sabha	Under Developed	Repair Boundary Wall / Paint
111	New Pream Nagar Opp House No. 37-A	20	8 Benches	130'X121'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
112	Deen Dayal Upadhaya Nagar Opp House No.24	20	7 Benches	148'X50'	1	Through Matching Grant	Deen Dayal Upadhaya Welfare Society	Under Developed	Repair Boundary Wall / Paint
113	Deen Dayal Upadhaya Nagar Opp House No.20	20	3 Benches, 1 Game, 1 Hut	75'X45'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
114	Deen Dayal Upadhaya Nagar Opp House No.19 (Ex. Mayor House)	20	5 Benches	111'X44'	1	Through Matching Grant	Deen Dayal Upadhaya Park Welfare Society	Developed	Repair Boundary Wall / Paint
115	Deen Dayal Upadhaya Nagar Tanki Wali Park	20	20 Benches, 1 Water Tank	174'X201'	1	Through Matching Grant	Deen Dayal Upadhaya Welfare Society	Developed	Repair Boundary Wall / Paint
116	Sat Nagar Opp House No.46	20	11 Benches, 1 Game	125'X85'	1	Through Matching Grant	Sat Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint
117	Purani Kachri Opp N.D 372	20	1 Tubewell	82'X56'	1	Through Matching Grant	Social Welfare Club Mohalla Purani Kachri	Under Developed	Repair Boundary Wall / Paint/ No Light / No Dustbin

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
118	Brij Nagar Opp House 5	20	6 Benches, 1 Game, 1 Tubewell	150'X132'	1	Through Matching Grant	Brij Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
119	Chandan Nagar Opp House. 9	20	5 Benches, 1 Game, 1 Tubewell	102'X60'X30'	1	Through Matching Grant	Chandan Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint
120	Mohalla Fathepuri Opp House No. 1	20	4 Benches, 4 Games	77'X56'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
121	Subash Nagar Opp House No. 40 Near Market	20	2 Benches	178'X65'	1	Through Matching Grant	Subash Nagar Welfare Society	Under Developed	No Games / No Dustbin
122	Chandan Nagar Opp House. 88	20	5 Games, 1 Bench	63'X52'	2	Through Matching Grant	Chandan Nagar Road Welfare Society	Under Developed	Repair Boundary Wall / Paint/ Grill Are Broken
123	Shiv Nagar, Opp.110	21	6 Benches	136'X51'	1	Through Matching Grant	Bhai Lalo Welfare Society	Under Developed	Repair Boundary Wall / Paint
124	Shiv Nagar, Opp.232	21	6 Benches	137'X50'	1	Through Matching Grant	Bhai Lalo Welfare Society	Under Developed	Repair Boundary Wall / Paint
125	Sodal Nagar, Opp. 198	21	No Bench	121'X85'	1	Through Matching Grant	Kumar Road & Park Welfare Society	Under Developed	Repair Boundary Wall / Paint
126	Shiv Nagar, Opp. 490	21	12 Benches	136'X111'X20'	1	Through Matching Grant	Bhai Lalo Welfare Society	Under Developed	Repair Boundary Wall / Paint
127	Shiv Nagar Opp. 263	21	11 Benches	77'X42'21"	1	Through Matching Grant	Bhai Lalo Welfare Society	Under Developed	Repair Boundary Wall / Paint
128	Shiv Nagar Opp House No. 353	21	8 Benches	147'X64'	1	Through Matching Grant	Bhai Lalo Welfare Society	Developed	Repair Boundary Wall / Paint
129	Shiv Nagar Opp House No. 191	21	6 Benches	111'X71'	1	Through Matching Grant	Bhai Lalo Welfare Society	Developed	Repair Boundary Wall / Paint
130	Shiv Nagar Opp House No. 134	21	11 Benches	130'X55'	1	Through Matching Grant	Bhai Lalo Welfare Society	Under Developed	Repair Boundary Wall / Paint/ Gate
131	Industrial Area Sardar Beant Singh Park Opp Jal Bypass.	21	1 Disposal, Quator, 1 Tubewell	1000'X300'X200'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
132	Sodal Nagar Opp House No. 140/2	22	4 Benches, 2 Games	97'X78'	1	Through Matching Grant	Shiv Shakti Welfare Society	Under Developed	Repair Boundary Wall / Paint
133	Sodal Nagar. Opp. Evt Model School	22	5 Benches 3 Concrete Benches	170'X82'	1	Through Matching Grant	The Glob Colony Welfare Society	Under Developed	Repair Boundary Wall / Paint
134	Sodal Nagar Opp Ebt Model School	22	5 Benches, 3 Conc Benches	170'X82'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
135	Sodal Nagar Opp. 104	22	8 Benches, 4 Conc Benches	238'X76'	1	Through Matching Grant	Sodal Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
136	Sodal Nagar, Opp. 230	22	1 Bench, Water Supply Is Not Good	117'X50'	1	Through Matching Grant	Children Welfare Society Sodal Nagar	Under Developed	Repair Boundary Wall / Paint
137	Sodal Nagar Nivia Park.	22	No Facilities	380'X275'	2	Through Matching Grant	Industrial Area Welfare & Development	Under Developed	Repair Boundary Wall / Paint
138	Sodal Shiv Shakti Park Opp House No. 104/2	22	9 Benches	97'X78'	1	Through Matching Grant	Sunrise Welfare Society	Under Developed	Repair Boundary Wall / Paint
139	Sodal Nagar Opp E.B.T Model School	22	5 Benches, 3 Games	170'X82'	1	Through Matching Grant	The Glob Colony Welfare Society	Under Developed	Repair Boundary Wall / Paint
140	Sodal Nagar Opp House No. 104 Ram Leela Ground.	22	8 Benches, 4 Games, 1 Stage	238'X76'	1	Through Matching Grant	Sodal Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
141	Shri Kirpal Singh Chawala Yadgar Park Preet Nagar Sodal Main Road.	22	1 Fountain, 1 Hut, 7 Benches	117'X72'	1	Through Agency	K.J Steel Rolling Mills Raowali Ptk Road	Developed	Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
142	Industrial Area Opp Police Station No. 1	22	25 Benches, 1 Hut, 4 Games	450'X200'	5	Through Matching Grant	Industrial Area Social Welfare Society	Under Developed	Repair Boundary Wall / Paint/ No Light
143	Dada Colony Opp Factory	22	16 Benches, 1 M.C Quator , 2 Hut, 10 Games	230'X190'	1	Through Matching Grant	Dada Colony Resident Social Welfare Society	Under Developed	Repair Boundary Wall / Paint
144	Dada Colony Opp Factory	22	1 Tubewell, 11 Benches, 5 Games	156'X132'	2	Through Matching Grant	Dada Colony Sudhar Sabha	Under Developed	Repair Boundary Wall / Paint/ Grill Are Broken
145	Dada Colony Backside M.C.J Zone	22	No Facilities	125'X100'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
146	Bagichi Tahpra Opp House. 227/7	22	4 Benches, 3 Games	140'X75'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
147	Bagichi Tahpra Opp House. 221/7	22	7 Benches, 4 Games	200'X81'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
148	Friends Colony ,Opp.77A/7	23	3 Benches	91'X70'	1	Through Matching Grant	Jan Ekta Welfare Society Kabir Nager	Developed	Repair Boundary Wall / Paint
149	Ram Nagar Shamshan Ghat Park Near Railway Line	23	3 Benches, 1 Tubewell, 2 Games	600'X175'	Nil	Through Society	Shamshan Ghat Society	Under Developed	Repair Boundary Wall / Paint
150	P & T Colony Opp 6	24	9 Benches	81'X59'	1	Through Matching Grant	P & T Welfare Society	Under Developed	Repair Boundary Wall/ Paint
151	Jain Colony Opp House No. 41-A	24	1 Tubewell, 8 Benches, 4 Games	85'X74'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint/ 3 Games Are Broken
152	Windson Park Opp House No. 21	24	11 Benches, 1 Tubewell	125'X70'	1	Through Matching Grant	Windson Park Welfare Society	Developed	Repair Boundary Wall / Paint
153	B.S.F Colony Tubewell Wali Park Opp House No. 176	24	1 Tubewell	110'X20'	1	Through Matching Grant	B.S.F Colony Welfare Society	No Developed	Repair Boundary Wall / Paint/ Grill Are Broken
154	B.S.F Colony Opp House No. 176	24	2 Benches	57'X28'	1	Through Matching Grant	B.S.F Colony Welfare Society	No Developed	Repair Boundary Wall / Paint
155	Bagh Bahriyan Opp House No. 22	24	4 Benches, 4 Games	85'X47'	1	Through Matching Grant	Bagh Bahriyan Welfare Society	Developed	Repair Boundary Wall / Paint
156	B.S.F Colony Opp House No. 37	24	2 Benches	35'X25'	1	Through Matching Grant	B.S.F Colony Welfare Society	No Developed	Grill Are Broken/ Repair Boundary Wall / Paint
157	Gurdev Nagar, Opp. 55	25	1 Fountain	175'X26'	1	Through Matching Grant	Mohalla Karar Khannagar Society	Under Developed	Repair Boundary Wall / Paint
158	Gopal Nagar Pili Kothi	26	6 Benches	74'X59'	1	Through Matching Grant	Social Welfare Society Gopal Nagar	Under Developed	Repair Boundary Wall/ Paint
159	Gopal Nagar Opp 333	26	1 Bench	113'X99'	1	Through Matching Grant	Social Welfare Society Gopal Nagar	Developed	Repair Boundary Wall/ Paint
160	Banda Bahader Nagar, Opp.35, Gullu Wali	26	16 Benches, Fountain	177'X50'	1	Through Matching Grant	Banda Bahader Welfare Society	Developed	Repair Boundary Wall / Paint
161	Banda Bahader Nagar, Opp. Tagore Hospital Main Road Mahavir Marg.	26	6 Benches	98'X75'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
162	Gopal Nagar, Opp. 133	26	9 Benches	142'X91'X11'	1	Through Matching Grant	Gopal Nagar Sudhar Sabha	Developed	Repair Boundary Wall / Paint
163	Gopal Nagar, Opp. 101-102	26	5 Benches	157'X70'	1	Through Matching Grant	Gopal Nagar Sudhar Sabha	Developed	Repair Boundary Wall / Paint
164	Shri Guru Ji Park, Gopal Nagar, Opp 165	26	No Facilities	96'X56'X20'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
165	Mahindra Mohalla Opp House No. 127 Near Market	27	3 Benches	35'X35'	-	Maintained By	Mohalla	Developed	Good

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
166	Charanjit Pura (Sarabh Hitkari Park) Near Gurr Mandi	28	11 Benches, 1 Fountain, 1 Gym Hall	140'X95'	-	Maintained By	Charanjit Pura Society	Developed	Repair Boundary Wall / Paint/ Required Games
167	Kot Bakshiyar Backside Raj Mehal Hotel	29	1 Tubewell	50'X30'	1	Through Matching Grant	Manav Mitra Welfare Society	Under Developed	Repair Boundary Wall / Paint
168	Shiva Ji Park Central Town	30	1 Tubewell, 1 Hut, 5 Games, 11 Benches	172'X98'X30'	1	Through Matching Grant	Shiva Ji Park Welfare Society	Under Developed	One Temple Inside/Repair Boundary Wall / Paint
169	Central Town Opp Sachar Hospital & House No. 8	30	5 Games, 9 Benches, 1 Fountain, 1 Hut, 1	140'X25'2'	2	Through Matching Grant	Mohalla Sudhar Sabha	Developed	Repair Boundary Wall / Paint
170	Central Town Opp House No.84/10 (Sh. Manmohan Kalia Park).	30	30 Benches, 6 Games, 3 Hut, 1 Fountain, 1 Library	154'X144'X132'	1	Through Matching Grant	Central Town Welfare Society	Developed	3 Games Are Broken/ Repair Boundary Wall / Paint
171	Guru Nanak Nagar Market Wali Park.Opp Govt. School Ladowali.	30	3 Benches	150'X95'X30'	1	Through Matching Grant	Guru Nanak Market Traders Machine'S Welfare Society	Under Developed	Repair Boundary Wall / Paint
172	Old Jawahar Nagar Opp House No. 26 Tanki Wali Park.	30	1 Fountain, 12 Benches,8 Games	164'X14'	2	Through Matching Grant	The Jawahar Nagar Welfare Society	Under Developed	Fountain Is Not Working.
173	Old Jawahar Nagar Opp House No. 9-A Park.	30	13 Benches, 1 Hut	192'X96'	1	Through Matching Grant	The Jawahar Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
174	Ramesh Colony Opp House No.	30	11 Benches, 1 Hut, 1 Tubewell	186'X10'2'	1	Through Matching Grant	Ramesh Colony Welfare Society	Developed	Repair Boundary Wall / Paint
175	Partap Bagh Opp Market	30	114 Benches, 14 Games, 2 Hut, 1 Fountain	402'X22'8'	3	Through Matching Grant	Partap Bagh Welfare Society	Developed	Games Are Broken/Repair Boundary Wall / Paint
176	Chahar Bagh Opp House No. 31 Near Phagwara Gate	30	6 Benches	63'X33'	1	Through Matching Grant	Chahar Bagh Welfare Society	Under Developed	Repair Boundary Wall / Paint
177	Arjun Nagar Opp House 24.	30	9 Benches, 1 Fountain, 1 Room, 1 Game	125'X95'	1	Through Matching Grant	Arjun Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint/ Repair Footpaht
178	Defence Colony, Opp House No. 176	31	3 Games, 4 Benches	184'X52'	1	Through Matching Grant	The Defence Colony Resident Society	No Developed	Benches Are Broken/Repair Boundary Wall / Paint
179	Defence Colony, Opp House No. 201	31	1 Bench	68'X32'	1	Through Matching Grant	The Defence Colony Resident Society	Developed	No Boundary Wall
180	Defence Colony,Market Wali,Opp Saint Joseph School	31	2 Benches	102'X41'	1	Through Matching Grant	The Defence Colony Resident Society	Under Developed	Repair Boundary Wall
181	Defence Colony Tanki Wali, Opp House No. 238	31	9 Benches,4 Games,1 Tubewell, 1 Water	370'X24'8'	1	Through Matching Grant	The Defence Colony Resident Society	Developed	Repair Boundary Wall/ Paint
182	Defence Colony,Tubewell Wali,Opp House No. 247	31	12 Benches , 5 Games,1 Hut	169'X12'8'	1	Through Matching Grant	The Defence Colony Resident Society	Developed	Repair Boundary Wall/ Paint
183	Defence Colony, Opp 247	31	7 Benches, 3 Games,	203'X64'	1	Through Matching Grant	The Defence Colony Resident Society	Developed	Repair Boundary Wall/ Paint
184	Defence Colony, Opp Tanki, House No. 175	31	1 Fountain	134'X99'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall/ Paint
185	Mohalla Ranjit Nagar Opp House No.	31	8 Games, 12 Benches, 1 Tubewell, 1	216'X14'7'	2	Through Matching Grant	Mohalla Ranjit Nagar Welfare Committee	Developed	Repair Boundary Wall / Paint
186	Ranjit Nagar Opp Gurudawara Sahib & House No. 107	31	7 Benches, 1 Community Hall	180'X50'	2	Through Matching Grant	Ranjit Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
187	New Baradari Near Gurudawara Sahib	31	1 Hut, 2 Games, 1 Room	65'X55'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
188	New Baradari Opp House No. 14	31	5 Benches, 3 Games	132'X12'0'	1	M.C.J	M.C.J	Under Developed	Grill Are Broken/ Repair Boundary Wall / Paint
189	New Baradri Opp House No.Block-A Set 1 To 10.	31	5 Benches	128'X10'4'	1	Through Matching Grant	New Baradri Welfare Society	Developed	Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
190	Rajinder Nagar Opp House No. 59.	31	8 Benches, 1 Hut	154'X91'	2	Through Matching Grant	Rajinder Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
191	Ranjit Nagar Opp House No. 60.	31	2 Benches, 2 Games	48'X36'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
192	Mastar Tara Singh Nagar Market Wali Park.	31	1 Fountain, 4 Benches	205'X115'	1	Through Bank	Uco Bank	Developed	Repair Boundary Wall / Paint
193	Mastar Tara Singh Nagar Opp House No. 296	31	1 Tubewell, 1 Bathroom	80'X45' X5'	1	Through Matching Grant	Master Tara Singh Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint
194	Mastar Tara Singh Nagar Opp House No. 342	31	10 Benches, 3 Games, 1 Hut	185'X125'X60'	1	Through Matching Grant	Master Tara Singh Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
195	Mastar Tara Singh Nagar Opp House No.111 Backside Market	31	5 Benches	250'X160'	1	Through Matching Grant	Neta Ji Park Welfare Society	Developed	Repair Boundary Wall / Paint
196	Mastar Tara Singh Nagar Neta Ji Park Opp House No. 25	31	14 Benches, 1 Hut, 6 Games	190'X95'	1	Through Matching Grant	Neta Ji Park Welfare Society	Developed	Repair Boundary Wall / Paint
197	Mastar Tara Singh Nagar Opp House No.98-99 Backside Market(Sondhi Wali Park)	31	1 Hut, 3 Games, 10 Benches	210'X55' X5'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
198	Dashmesh Nagar, Opp House No. 15	32	9 Benches, 1 Hut, 3 Games	136'X51'	1	Through Matching Grant	Dashmesh Nagar Welfare Society	Developed	Repair Boundary Wall/ Paint
199	Hardayal Nagar Tubewell Wali Park Opp House No.. 179	32	1 Tubewell, 2 Games, 1 Bench	80'X76'	1	Through Matching Grant	Hardayal Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint
200	Gurjit Nagar Opp House No.. 132	32	1 Hut, 8 Benches, 4 Games	80'X46'	1	Through Matching Grant	The Citizen Social Welfare Society Gurjit Nagar	Developed	Repair Boundary Wall / Paint
201	Hardayal Nagar Opp House No. 150	32	3 Benches, 1 Game	90'X80'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
202	Makhdumpura Dhobi Wali Park Near Shiv Mandir Opp House No. 16	32	8 Benches, 3 Games	98'X33'	1	Through Matching Grant	Makhdumpura Welfare Society	Under Developed	Games Are Broken/ Repair Boundary Wall & Paint
203	Urban State Phase 1 Opp House No.. 1014 Near Raiway Line	33	No Games	191'X93' X29'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
204	Golden Avenue Phase 2 Opp House No..26	33	1 Tubewell, 4 Benches, Games	115'X111'	1	Through Matching Grant	Golden Avenue Phase 2 Welfare Society	Developed	Repair Boundary Wall / Paint
205	Urban State Phase 1 Opp House No. 226 Near Raiway Line	33	No Facilities	546'X331'X215'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
206	Urban State Phase 1 Opp Satguru Kabir Park No 13	33	2 Games, 7 Benches	172'X34'	1	Through Matching Grant	Naujawan Sabha Dharamshala Committee Ph-1	Developed	Repair Boundary Wall / Paint
207	Urban State Phase 1 Opp House No.. 80	33	No Facilities	328'X250'X200'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
208	Urban State Phase 1 Tubewell Wali Park Opp House No.. 8	33	No Facilities	125'X65' X89'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint/ Grill Is Broken
209	Urban State Phase 1 Opp H.P Gass Kaniya Wali Park	33	4 Benches	213'X51'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
210	Urban State Phase 1 Opp House No. 288 Kaniya Wali Park	33	No Facilities	263'X31' X8'	Nil	M.C.J	M.C.J	No Developed	No Footpathrepair Boundary Wall / Paint
211	Urban State Phase 1 Opp 227/13 Labour Colony	33	4 Benches	74'X74'	1	Through Matching Grant	Jagrati Welfare Society Labour Colony	No Developed	Repair Boundary Wall / Paint
212	Urban State Phase 1 Opp House No.. 20 Labour Colony	33	2 Games, 5 Benches	85'X82'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
213	Urban State Phase 1 Opp House No.. 121- C Park No. 11	33	7 Benches, 2 Games	172'X28'	1	Through Matching Grant	Yuva Jan Shakti Murcha	Developed	Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
214	Urban State Phase 1 Opp House No.. 86	33	No Facilities	122'X14 8'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
215	Urban State Phase 1 Opp House No.. 214	33	No Facilities	142'X11 1'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
216	Housing Board Colony Near Railway Line	33	No Facilities	94'X62'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
217	Urban State Phase 1 Opp House No.. 175 Near H.I.G Apartment Park No.9	33	4 Games, Benches	303'X95 'X18	1	Through Matching Grant	H.I.G Apartment Welfare Society	Developed	Repair Boundary Wall / Paint
218	Urban State Phase 1 Opp House No.. 219 Park No 10	33	6 Benches, 1 Game	102'X67 '	1	Through Matching Grant	H.I.G Apartment Welfare Society	Developed	Repair Boundary Wall / Paint
219	Urban State Phase 1 Opp House No.. 433 Park No. 12	33	1 Hut, 16 Benches, 4 Games	188'X12 9'	2	Through Matching Grant	Yuva Jan Shakti Murcha	Developed	Repair Boundary Wall / Paint
220	Urban State Phase 1 Opp House No. 471	33	2 Benches	158'X38 '	1	Through Matching Grant	Yuva Jan Shakti Murcha	Under Developed	Repair Boundary Wall / Paint
221	Urban State Phase 1 Opp House No.. 799 Park No.6	33	3 Games	125'X16 5'	1	Through Matching Grant	Yuva Jan Shakti Murcha	Under Developed	Repair Boundary Wall / Paint
222	Urban State Phase 1 Opp House No.. 644 Park No. 7	33	8 Benches	186'X13 4'	1	Through Matching Grant	Yuva Jan Shakti Murcha	Developed	Repair Boundary Wall / Paint
223	Urban State Phase 1 Opp House No.. 798	33	No Facilities	648'X10 3'	Nil	M.C.J	M.C.J	No Developed	A Store & M.C Quator/Repair Boundary Wall / Paint
224	Urban State Phase 1 Opp House No.. 676	33	No Facilities	90'X88'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
225	Urban State Phase 1 Opp House No.. 159 Park No. 8	33	6 Benches, 4 Games	190'X15 2'	1	Through Matching Grant	Urban State Welfare Society	Under Developed	Repair Boundary Wall / Paint
226	Urban State Phase 1 Opp House No.. 1054-A Park No. 1	33	12 Benches	405'X10 7'	1	Through Matching Grant	Urban State Welfare Society	Developed	Repair Boundary Wall / Paint
227	Urban State Phase 1 Opp House No.. 1152 Park No. 2	33	2 Games, 24 Benches, 1 Hut	300'X15 4'	1	Through Matching Grant	Urban State Welfare Society	Developed	Repair Boundary Wall / Paint
228	Urban State Phase 1 Opp House No.. 1252 Park No. 3 Cambridge School	33	13 Benches, 3 Games	256'X23 0'	1	Through Matching Grant	Urban State Welfare Society	Developed	Repair Boundary Wall / Paint
229	Urban State Phase 1 Opp House No.. 728 Park No. 5	33	15 Benches, 1 Hut	262'X10 4'	1	Through Matching Grant	Urban State Welfare Society	Under Developed	Repair Boundary Wall / Paint
230	Urban State Phase 1 Opp House No.821 Park No. 4	33	1 Fountain, 7 Games, 15 Benches	228'X19 8'	1	Through Matching Grant	Urban State Welfare Society	Developed	Repair Boundary Wall / Paint
231	Garha Zone Tubewell Wali Park	33	1 Tubewell, 1 Water Tank, 1 B&R Zone Office	200'X14 5'	Nil	M.C.J	M.C.J	No Developed	Only Boundary Required To Paint
232	Green Park Opp. Link Road	34	3 Games, 7 Benches, 1 Tubewell	200'X11 5'	1	Through Matching Grant	The Green Park Welfare Society	Developed	Repair Boundary Wall / Paint
233	Mota Singh Nagar Opp. Bus Stand	34	6 Benches, 1 Temple	215'X21 1X85' (3-D)	1	Through Matching Grant	Mota Singh Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
234	Mota Singh Nagar Near Bus Stand Opp. House No.. 697	34	17 Benches, 5 Games, 1 Hut, 1 Community Hall	270'X75 '	1	Through Matching Grant	Mota Singh Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
235	Mota Singh Nagar Opp. Shiv Mandir House No. 592	34	17 Benches, 6 Games, 1 Hut, 1 Tubewell	315'X95 '	1	Through Matching Grant	Mota Singh Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint
236	Mota Singh Nagar Near Cool Road, House No.. 542	34	1 Hut, 6 Games, 15 Benches	210'X11 5'	1	Through Matching Grant	Mota Singh Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint
237	Mota Singh Nagar Main Park Opp. House No. 446	34	1 Tubewell, 1 Hut, 28 Benches, 5 Games	340'X19 5'	1	Through Matching Grant	Mota Singh Nagar Welfare Society	Developed	Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
238	Mota Singh Nagar Opp. House No. 646 Shaheed Udhm Singh Park	34	1 Hut, 19 Benches, 7 Games	150'X100'	1	Through Matching Grant	Mota Singh Association	Developed	Repair Boundary Wall / Paint
239	Mota Singh Nagar Opp. House No. 370 To 375	34	17 Benches, 7 Games	175'X165'	1	Through Matching Grant	Mota Singh Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
240	New Jawahar Nagar Market Park	34	4 Benches, 4 Games	90'X85'X18'	1	Through Matching Grant	New Jawahar Nagar Welfare Association	Under Developed	Repair Boundary Wall / Paint
241	New Jawahar Nagar Jagrata Wali Park Opp House No. 444	34	1 Hut, 2 Games, 12 Benches	320'X154'	2	Through Matching Grant	Main Park New Jawahar Nagar Welfare Society	Developed	Gate & Grill Are Broken Repair Boundary Wall / Paint
242	New Jawahar Nagar Opp House No. 79 Govt. Primary School Park.	34	23 Benches, 7 Games, 1 Tubewell	356'X167'	2	Through Agency	Chamunda Devi Mandir Welfare Society	Developed	Games Are Broken
243	Modern Colony Near N.J Nagar Backside Opp Devi Mandir Opp House No. 34	34	17 Benches, 4 Games	282'X100'	1	Through Matching Grant	Modren Colony Welfare Society	Developed	Repair Boundary Wall / Paint
244	Bank Colony New Jawahar Nagar Opp. House No. 10	34	5 Games, 24 Benches	300'X84'	1	Through Matching Grant	New Jawahar Nagar Bank Colony Welfare Society	Developed	Repair Boundary Wall / Paint
245	Badri Dass Colony Backside Desh Bhagat Singh Hall Opp House No. 33	34	9 Benches, 5 Games	333'X157'X50 (3-D)	1	Through Matching Grant	Badri Dass Colony Welfare Society	Developed	Repair Games/ Boundary Wall / Paint
246	Green Park Opp Bus Stand	34	23 Benches, 6 Games	448'X283X85'	2	Through Matching Grant	Green Park Welfare Society	Under Developed	Games Are Broken
247	New Jawahar Nagar Tanki Wali Park Opp. 466 Near Guru Gobind Singh Stadium	34	21 Benches, 6 Games, 1 Tubewell , 1 Hut	525'X116'X69	2	Through Matching Grant	New Jawahar Nagar Welfare Society	Developed	Repair Boundary Wall / Paint/Games Are Broken
248	Lajpat Nagar Opp. House No. 286-L Nehar Wali Park.	34	2 Benches,	107'X32'X30'	1	Through Matching Grant	Lajpat Nagar Resident Welfare Society East	Developed	Repair Boundary Wall / Paint
249	Lajpat Nagar Opp House No. 285 Nehar Wali Park.	34	5 Games, 6 Benches	107'X39'	1	Through Matching Grant	Lajpat Nagar Resident Welfare Society East	Developed	Repair Boundary Wall / Paint
250	Lajpat Nagar Opp House No. 281 Nehar Wali Park.	34	1 Tubewell, 1 Hut, 26 Benches, 3 Games	490'X49'	2	Through Matching Grant	Lajpat Nagar Resident Welfare Society East	Developed	Excellent
251	Lajpat Nagar Nehar Wali Park.	34	No Facilities	89'X34'18	1	M.C.J	M.C.J	Developed	No Grill On Boundary Wall
252	Lajpat Nagar Nehar Wali Park.	34	No Facilities	25'X18'	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall
253	Lajpat Nagar Nehar Wali Park.	34	No Facilities	130'X25'	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall
254	Lajpat Nagar Tubewell Wali Park.	34	1 Tubewell, M.C Quator, 9 Games, Benches 5	363'X142'	2	Through Matching Grant	Lajpat Rai Nagar Welfare Association	Under Developed	Games Are Broken/ Repair Boundary Wall / Paint
255	Lajpat Nagar Backside St Josep Nursery School Opp House No.. 251 Nehar Wali	34	9 Games	525'X100'X60'	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall
256	Lajpat Nagar North Backside Petrol Pump (Rose Park)	34	1 Tubewell, 2 Hut, 1 Fountain, 35 Benches, 5	500'X231'	2	Through Matching Grant	Lajpat Nagar North Welfare Society	Developed	Repair Boundary Wall / Paint
257	Police Line Near B.M.C Chowk Park.1	34	1 Tubewell , 2 Benches	326'X61'	1	Through Matching Grant	Park Development & Welfare Society Police Line	Developed	Repair Boundary Wall / Paint
258	Police Line Near B.M.C Chowk Park.2	34	1 Bathroom	126'X115'X110'	Nil	M.C.J	M.C.J	No Developed	Boundary Wall Broken
259	Old Baradari Opp House No.. 32-B	34	4 Games	164'X108'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
260	Old Baradari Opp D.C Resident	34	17 Benches, 1 Hut, 13 Games, Mc Quator	151'X231'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
261	Opp Mahavir Marg Near Tv Centre	35	5 Benches, All	522'X70'X8'	2	Through Matching Grant	Shahedd Udhm Singh Nagar Welfare Society	Developed	Repair Boundary Wall/ Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
262	Shaheed Udham Singh Opp 337	35	12 Benches, 1 Fountain	360'X100'	2	Through Matching Grant	Shaheed Udham Singh Nagar Welfare Society	Developed	Repair Boundary Wall/ Paint/ Fountain Is Not Work
263	Shaheed Udham Singh Nagar Opp House No. 353	35	7 Benches, 6 Games	110'X63'X12'	1	Through Matching Grant	Shaheed Udham Singh Nagar Welfare Society	Under Developed	No Footpaht/ Repair Boundary Wall & Paint
264	Ajit Nagar Opp House No. 1193	35	7 Games, 10 Benches	85'X73'	1	Through Matching Grant	Ajit Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
265	Shaheed Udham Singh Nagar Opp House No. 120 (Pathar Wali Park)	35	31 Benches, 1 Hut, 8 Games, 1 Shiv Mandir, 1 Mcj	363'X135'	1	Through Matching Grant	Shaheed Udham Singh Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
266	Opp Jain Sen Sec School, Vijay Nagar.	36	25 Benches, 1 Water Tank	281'X229'	2	Through Matching Grant	Vijay Nagar Woman Society	Developed	Repair Boundary Wall/ Paint
267	Shakti Nagar , Opp 47	36	60 Benches, All	253'X90'	2	Through Matching Grant	Shakti Nagar Welfare Society	Developed	Repair Boundary Wall/ Paint
268	Shakti Nagar, Opp186	36	15 Benches, All	243'X120'	2	Through Matching Grant	Shakti Nagar Welfare Society	Developed	Repair Boundary Wall/ Paint
269	Shakti Nagar Opp 141.	36	15 Benches	200'X86'	2	Through Matching Grant	Shakti Nagar Welfare Society	Developed	Repair Boundary Wall/ Paint
270	Mohalla Islamganj Opp Peer Dargah & House No. W-G 81/1	36	No Facilities	150'X100'	Nil	M.C.J	M.C.J	No Developed	Boundary Wall Is Broken, No Grill
271	New Vijay Nagar Balwant Rai Park	37	1 Hut, 15 Benches, 4 Games	205'X71'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
272	Adarsh Nagar Main Market Wali Park.	37	55 Benches, 7 Games, 1 Hut, 1 Tubewell, Mc	475'X241'	2	Through C.T Institute	C.T	Developed	Repair Boundary Wall / Paint
273	Adarsh Nagar Main Market Wali Park Second Site	37	1 Fountain, 1 Game, Tubewell, 1 Milk Bar, 3	241'X100'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
274	J.P Nagar Opp House No..376 Near Mobile Tower	37	10 Benches, 4 Games, 1 Hut	117'X105'X88'	1	Through Matching Grant	J.P Nagar People Welfare Association	Developed	Repair Boundary Wall / Paint
275	Harbhans Nagar Opp House No.. 66-B	37	1 Tubewell, 17 Benches, 6 Games, 2 Hut	121'X92'	1	Through Matching Grant	Harbhans Nagar Welfare Society	Under Developed	1 Gym Inside, Repair Boundary Wall / Paint
276	J.P Nagar Opp House No..306 Near Sh Bhagat Chunni Lal House (Minister	37	1 Hut, 23 Benches, 11 Games	259'X175'	1	Through Matching Grant	J.P Nagar People Welfare Association	Developed	Repair Boundary Wall / Paint
277	J.P Nagar Opp House No..526 Tanki Wali Park Near Sant Sawami Dass Public	37	18 Benches, 2 Games	260'X115'	1	Through Matching Grant	Harbhans Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
278	J.P Nagar Apna Park Opp House No. 472	37	1 Tubewell, 21 Benches, 7 Games, 2 Hut, 1	245'X135'	1	Through Matching Grant	J.P Nagar People Welfare Society	Developed	Excellent
279	Adarsh Nagar Dhusshra Ground Opp House No..23	37	1 Tubewell, 30 Benches, 10 Games, 2 Hut	260'X218'	2	Through Matching Grant	Adarsh Nagar Shabha	Developed	Repair Boundary Wall / Paint
280	New Vijay Nagar Near House No. 15/135	37	1 Hut, 5 Games, 12 Benches	114'X82'	1	M.C.J	M.C.J	Developed	Benches Are Broken/Repair Boundary Wall / Paint
281	New Vijay Nagar Near House No. 186/199	37	2 Hut, 1 Tubewell, 21 Benches, 9 Games	272'X120'X110'	2	Through Matching Grant	Adarsh Nagar Shabha	Under Developed	Repair Boundary Wall / Paint
282	New Vijay Nagar Near House No. 21-A/228	37	1 Library, 1 Bathroom, 1 Temple, 6	150'X100'	2	Through Matching Grant	Adarsh Nagar Shabha	Developed	Repair Boundary Wall / Paint
283	Tagore Nagar Opp House No. 17	37	5 Benches, 6 Games	150'X70'	2	Through Matching Grant	Gujral Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
284	Tagore Nagar Opp House No. 22	37	3 Games, 4 Benches, 1 Community Hall , 1	95'X53'	1	Through Matching Grant	Tagore Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint/ No Grass
285	Saraswati Vihar, Opp 78 Gf	38	7 Benches	92'X67'	1	Through Matching Grant	Sarswati Vihar Welfare Society	Under Developed	Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
286	Saraswati Vihar Opp 12 Gf	38	12 Benches	256'X100'	2	Through Matching Grant	Sarswati Vihar Welfare Society	Developed	Repair Boundary Wall / Paint
287	Saraswati Vihar,Opp Manmohan Kalia, Community Centre	38	All Facility	110'X42'X98'	2	Through Matching Grant	Sarswati Vihar Welfare Society	Developed	Repair Boundary Wall / Paint
288	Saraswati Vihar Opp 6 Gf	38	2 Benches	57'X43'	1	Through Matching Grant	Saraswati Vihar Welfare Society	Developed	Repair Boundary Wall / Paint
289	Adarsh Nagar Bolina Park Opp House No. 368	38	1 Fountain, 2 Hut, 1 Tubewell, 22 Benches, 9 Games	210'X191'	1	Through Matching Grant	Adarsh Social & Environmental Society	Developed	Repair Of Fountain Boundary Wall / Paint
290	Burton Park (Rose Park)	38	No Facilities	510'X325'	3	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
291	Burton Park Opp Cricket Stadium	38	26 Benches, 1 Hut, 4 Games	450'X355'	6	Through Matching Grant	Burton Park Welfare Society	Developed	No Boundary Wall
292	Burton Park Opp. Hockey Stadium	38	3 Benches, 1 Tens Ground	828'X175'	2	Through Matching Grant	Rotary Club	Developed	Only One Side Boundary Wall
293	Apahaj Ashram Near H.M.V College	38	No Facilities	94'X65'	1	Through Matching Grant	Apahaj Ashram Apahaj Sahaik Sabha	Developed	No Boundary Wall
294	Greater Kailash Opp House No. 222	39	9 Benches, 1 Tubewell, 1 Hut	179'X101'	1	Through Matching Grant	Greater Kailash Welfare Society	Developed	Repair Boundary Wall / Paint
295	Greater Kailash Opp House No. 347	39	7 Benches, 5 Games, 1 Water Tank, 1 Tubewell,	248'X170'	1	Through Matching Grant	Greater Kailash Welfare Society	Developed	Repair Boundary Wall / Paint
296	Shanti Vihar Maqsudan Opp. House No. 305	39	5 Benches, 1 Game	160'X48'	1	Through Matching Grant	The Friends Co-Op House Building Society	Developed	Boundary Wall High Low Without Grill
297	Shanti Vihar Maqsudan Opp. House No. 277-A	39	4 Benches, 1 Game	155'X15'	1	Through Matching Grant	The Friends Co-Op House Building Society	Developed	Boundary Wall High Low Without Grill
298	Shanti Vihar Maqsudan Opp. House No. 93-94	39	4 Games	75'X55'	1	Through Matching Grant	The Friends Co-Op House Building Society	Developed	Boundary Wall High Low Without Grill
299	Shanti Vihar Maqsudan Opp. House No. 224	39	5 Games, 2 Benches	80'X70'	1	Through Matching Grant	The Friends Co-Op House Building Society	Developed	Only One Side Grill On Boundary Wall, Wall High Is Low
300	Shanti Vihar Maqsudan Opp. House No. 138	39	1 Games, 4 Games	150'X73'	Same Here↑	Through Matching Grant	The Friends Co-Op House Building Society	Developed	Boundary Wall High Low Without Grill
301	Shanti Vihar Maqsudan Opp. House No. 179	39	4 Games, 1 Benches	148'X100'	Same Here↑	Through Matching Grant	The Friends Co-Op House Building Society	Developed	No Grill, No Light, No Bench
302	Shanti Vihar Maqsudan Opp. House No. 241	39	6 Games, 1 Bench	148'X75'	Same Here↑	Through Matching Grant	The Friends Co-Op House Building Society	Developed	No Grill, No Light, No Bench
303	Shanti Vihar Maqsudan Opp. House No. 66	39	1 Tubewell, 3 Games	75'X18'	Same Here↑	Through Matching Grant	The Friends Co-Op House Building Society	Developed	Boundary Wall High Low Without Grill
304	Shanti Vihar Maqsudan Opp. House No. 117	39	2 Benches, 4 Games	155'X105'	Same Here↑	Through Matching Grant	The Friends Co-Op House Building Society	Developed	Boundary Wall High Low Without Grill
305	Vivaka Nand 3-D Park Maqsudan Opp. House No. 245 To 264 Park No.5	39	1 Hut, 4 Games, 4Benches, 1 Tubewell &	270'X175'	1	Through Matching Grant	The Lig Mig Co-Op House Building Society	Developed	Repair Boundary Wall / Paint/ No Light, No Distbin
306	Vivaka Nand Maqsudan Opp. House No. 15 Park No.1	39	4 Games, 4 Benches, One Society Room, 1	120'X85'	1	Through Matching Grant	The Lig Mig Co-Op House Building Society	Developed	Repair Boundary Wall / Paint/ No Light, No Distbin
307	Golden Avenue Maqsudan Opp House No. 19-A	39	4 Games	200'X135'	1	M.C.J	M.C.J	Developed	Boundary Wall Is Broken And Game Are Broken, No Grill
308	Vivaka Nand Maqsudan Opp. House No. 100 Park No.2	39	4 Benches, 4 Games, 1 Hut	60'X60'	Same Here↑	Through Matching Grant	The Lig Mig Co-Op House Building Society	Under Developed	Repair Boundary Wall / Paint/ No Light, No Distbin
309	Vivaka Nand Maqsudan Opp. House No. 73 Park No.3	39	1 Tubewell, 1 Hut, 4 Benches	190'X94'	Same Here↑	Through Matching Grant	The Lig Mig Co-Op House Building Society	Developed	Repair Boundary Wall / Paint/ No Light, No Distbin

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
310	Vivaka Nand Maqsudan Opp. House No. 128 Park No.8	39	1 Hut, 6 Games, 4 Benches	205'X60'	Same Here↑	Through Matching Grant	The Lig Mig Co-Op House Buildeeng Society	Developed	Repair Boundary Wall / Paint/ No Light, No Distbin
311	Tagore Park Opp House No. 11 Near Maqsudan Police Station	39	4 Benches, 2 Games	105'X40'	2	Through Matching Grant	National Park Welfare Society Maqsudan	Developed	Repair Boundary Wall / Paint
312	Greater Kailash Opp House No. 180-181	39	5 Benches, 2 Games	120'X63'	1	Through Matching Grant	Greater Kailash Welfare Society	Developed	Repair Boundary Wall / Paint
313	Sudarshan Park Colony Opp House No. 146	39	1 Tubewell, 4 Benches, 10 Games	200'X150'	1	Through Matching Grant	Sudarshan Park Colony Welfare Society	Developed	No Boundary Wall/ No Light/ No Footpath
314	Shiv Nagar Near Babu Labh Singh Nagar Backside Railway Fatak	40	No Facilities/ One Electricity Transformer Inside	45'X30'	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall
315	New Ratan Nagar Near Ganda Nala	40	2 Benches, 1 Tubewell	70'X50'	1	Through Matching Grant	Mohalla Welfare Society New Ratan Nagar	Under Developed	Repair Boundary Wall
316	Guru Nanak Nagar Tubewell Wali Park	40	1 Tubewell, 2 Benches	150'X100'	1	Through Matching Grant	Guru Nanak Nagar Welfare Society	Under Developed	Repair Boundary Wall
317	New Guru Nanak Nagar Tubewell Wali Park.	40	1 Tubewell, 2 Benches	150'X60'	1	Through Matching Grant	Guru Nanak Nagar Welfare Society	Under Developed	Repair Boundary Wall
318	Madhuban Colony Opp Market	41	15 Benches, 1 Tubewell, 1 Dispensary	193'X90'X43	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall
319	Kacha Kot Basti Bawa Khel Near Church	42	1 Tubewell, 3 Benches	122'X159'	Nil	M.C.J	M.C.J	No Developed	No Boundary Wall /Broken Gate
320	Kacha Kot Basti Bawa Khel (Tanki Wali Park)	42	No Facilities	158'X142'	Nil	M.C.J	M.C.J	No Developed	M.C Quator,Grill Are Broken Repair Boundary Wall / Paint
321	Old Green Avenue Opp House No.. 37	42	No Facilities	189'X118'	1	Through Matching Grant	Green Avenue Welfare Society	Under Developed	Repair Boundary Wall / Paint
322	Baba Budha Ji Nagar Opp Basti Bawa Khel Nehar.	42	12 Benches, 4 Games, 1 Hut	195'X45'X5'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
323	Harbhans Nagar Near Market Harji Park Opp House No.44-A	43	1 Tubewell, 18 Benches, 7 Games	225'X125'25'	1	Through Matching Grant	H.S Harji Park Development Society	Under Developed	Repair Boundary Wall / Paint/ Games Are Broken
324	Shashtri Nagr Opp House No . 87	43	1 Tubewell, 2 Benches, 2 Games	90'X55'	1	Through Matching Grant	Shashtri Nagar Welfare Society	Developed	No Light, Games Are Broken/ Repair Boundary Wall / Paint
325	Basit Guzan Shakti Park Tanki Wali.	44	2 Hut, 1 Tubewell, 1 Water Tank (Health Zone)	175'X145'	2	Through Matching Grant	Bhagwan Valmik Shakti Park Wefare Society	No Developed	No Grass/ Repair Boundary Wall & Game
326	Virdi Colony Opp House No.. 30	44	14 Benches, 3 Games, 1 Hut	103'X79'	1	Through Matching Grant	Virdi Colony Welfare Society	Under Developed	Repair Boundary Wall / Paint
327	Dilbagh Nagar Extension Opp House No. 380-B	45	5 Benches, 2 Games, 1 Tubewell, 1 Water	119'X70'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
328	Basti Guzan 120 Futti Road Children Park	45	1 Hut, 4 Games, 7 Benches	120'X90'	1	Through Matching Grant	Freedom Fighter Wazir Chand Atish Park	Developed	Game Are Broken/Repair Boundary Wall / Paint
329	Basti Guzan 120 Futti Road Near Babu Jagg Jeevan Ram Chowk	45	No Facilities	110'X110'X90'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
330	Dilbagh Nagar Opp House No. D-1 & 14 -D	45	12 Benches, 1 Tubewell, 1 Room, 3 Games	90'X78'	1	Through Matching Grant	Dilbagh Nagar Welfare Society	Under Developed	Game Are Broken/Repair Boundary Wall / Paint
331	Dilbagh Nagar Extension Opp House No. 94	45	21 Benches, 7 Games, 1 Tubewell	144'X102'	1	Through Matching Grant	Dilbagh Nagar Extension Chhota Park Welfare	Developed	Repair Boundary Wall / Paint
332	New Rasela Nagar Opp House No. 43/A	45	1 Tubewell, 5 Benches	112'X325'	1	Through Matching Grant	New Rasela Nagar Welfare Society	Developed	Game Are Broken/Repair Boundary Wall / Paint
333	Basti Guzan 120 Futti Road Mahant Agya Singh Park	45	3 Hut, 43 Benches, 1 Fountain	265'X25'	1	Through Matching Grant	Freedom Fighter Mahant Agya Singh Park Welfare	Developed	Fountain Need To Repair / Games Are Broken

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
334	Sat Ram Grower Park 120 Road Basti Guzan	45	8 Benches, 2 Games, 1 Hut	78'X72'	1	Through Matching Grant	Chaudhary Sat Ram Grower Park Welfare Society	Under Developed	Only Boundary Wall Without Grill/ Paint
335	Basti Guzan Chaudhary Sat Ram Park	45	2 Games, 1 Hut	66'X48'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
336	Basti Guzan Opp Arya Senior Secondary School	45	1 Tubewell	90'X48'8"	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
337	Basti Danishmanda Shamshan Ghat	46	3 Benches, 8 Games	63'X40'	1	Through Matching Grant	Danishmanda Welfare Society	Developed	No Boundary Wall/ No Light
338	Adda Basti Danishmanda Near Gurudawara Sahib	46	4 Benches	62'X50'	1	M.C.J	M.C.J	No Developed	Repair Water Cooler & Bench
339	Rasela Nagar Opp House No. 103	46	8 Benches, 1 Tubewell, 2 Games	102'X55'	1	Through Matching Grant	Mahela Welfare Society	Under Developed	Repair Boundary Wall / Paint
340	Basti Shekh Opp House No. 143 Bgn Dhushshara Ground	47	No Facilities	400'X265'	2	Through Matching Grant	Dhushshara Ground Welfare Society	Under Developed	Repair Boundary Wall / Paint/ Small Gate Is Broken
341	Basti Shekh Hargobind Colony Opp House No. 105	47	5 Benches	131'X72'	1	Through Matching Grant	Guru Nanak Park Welfare Society	Under Developed	Repair Boundary Wall / Paint
342	Basit Shekh Guru Nanak Tubewell Wali Park.	47	8 Benches, 5 Games, 1 Hut, 1 Tubewell, 1 M.C	300'X200'	3	Through Matching Grant	Guru Nanak Dev Ji Welfare Society	Under Developed	Repair Boundary Wall / Paint/ No Lights, Games Are Broken
343	Satra Mohalla Basti Shekh Tubewell Wali Park.	47	1 Hut, 1 Tubewell, 5 Benches	137'X73'	2	Through Matching Grant	Satra Mohala Welfare Society	Under Developed	Grill Are Broken/ Repair Boundary Wall / Paint
344	Model House Opp 85L/A	48	4 Benches	81'X50'22'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Under Developed	Repair Boundary Wall/ Paint
345	Model House Near Basant Ice Cream Gopal Das Park	48	4 Benches , All	116'X39'X17'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Under Developed	Repair Boundary Wall/ Paint
346	Model House Near Gurudwara Singh Sabha Market	48	5 Benches, All	146'X233'	2	Through Matching Grant	Punjabi Culture & Welfare Society	Under Developed	Repair Boundary Wall/ Paint
347	Karam Chand Market, Model House Ghully Di Chakki	48	6 Benches	100'X50'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Under Developed	Repair Boundary Wall/ Paint
348	Model House Block-C Opp 22R	48	6 Benches	135'X79'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Under Developed	Repair Boundary Wall/ Paint
349	Shani Mandir Model House	48	5 Benches	161'57'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Under Developed	Repair Boundary Wall/ Paint
350	Bhagat Singh Nagar Opp 907	48	5 Benches, 1 Tubewell	90'X40'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Developed	Repair Boundary Wall/ Paint
351	Bhagat Singh Nagar Opp Fm 236	48	4 Benches	106'X55'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Under Developed	Repair Boundary Wall/ Paint
352	Model House , Opp Fm 221	48	4 Benches	105'X56'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Under Developed	Repair Boundary Wall/ Paint
353	Opp Fm 82	48	4 Benches	142'X82'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Developed	Repair Boundary Wall/ Paint
354	M H Opp Laxmi Narayan Mandir	48	17 Benches	234'X119'	1	Through Matching Grant	Punjabi Culture & Welfare Society	Developed	Repair Boundary Wall/ Paint
355	Model House Noorpuri	48	7 Benches	140'X85'	1	Through Agency	National Switch Gear 133 Model House	Developed	Repair Boundary Wall/ Paint
356	Model House Nand Lal Park Bhagat Singh Nagar	48	3 Benches	159'X68'	1	Through Agency	National Switch Gear 133 Model House	Developed	Repair Boundary Wall/ Paint
357	Nijatam Nagar Opp House No. 15	49	3 Games, 14 Benches, 1 Tubewell, 1 Hut	108'X108'	1	Through Matching Grant	Nijatam Nagar Welfare Society	Developed	Games & Grill Are Broken/No Light Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
358	Avtar Nagar Main Road Back Side T.V Centre	51	6 Benches, 1 Hut	445'X18'	1	Through Matching Grant	Avtar Nagar Welfare Society	No Developed	Grill Are Broken/ Repair Boundary Wall / Paint
359	Bhargo Nagar Budha Mall Park	52	1 Tubewell, 1 Water Tank, 50 Benches, 8	250'X250'	2	Through Matching Grant	The Bhagat Budha Mall Welfare Society	Developed	Repair Boundary Wall / Paint & Fountain
360	Link Colony Opp House No. 53	53	1, Tubewell, 10 Benches	221'X57'	2	Through Matching Grant	Grow Green Society Abadpura	Under Developed	Repair Boundary Wall / Paint
361	Guru Ravidass Nagar Opp House No. 187	53	1 Hut, 20 Benches, 2 Games	213'X139'	2	Through Matching Grant	Grow Green Society Abadpura	Developed	Repair Boundary Wall / Paint
362	Shri Guru Ravidass Nagar Opp House No. 61	53	5 Benches	105'X99'	2	Through Matching Grant	Grow Green Society Abadpura	Under Developed	Repair Boundary Wall / Paint
363	Bank Colony Opp House No. 801/10	53	1 Hut, 11 Benches, 3 Games	192'X64'	2	Through Matching Grant	Bank Colony Road Welfare Society	Developed	Repair Boundary Wall / Paint
364	Abadpura Shamshan Ghat Near Link Colony Opp House. No. 316	53	11 Benches, 1 Hut	115'X115'	1	Through Matching Grant	Mohalla Shamshan Ghat Sudhar Committee	Under Developed	Repair Boundary Wall / Paint
365	Dr. B.R Ambedkar Boota Mandi Park Nakodar Road	54	40 Benches, 1 Fountain, 2 Hut	500'X200'X190'	3	Through Matching Grant	Dr. B.R Ambedkar Welfare Society	Under Developed	Fountain Is Not Work, Gate Is Broken
366	State Bank Colony Opp House No. 9	54	3 Benches, 3 Games	126'X84'	1	Through Matching Grant	Bank Colony Welfare Society	Developed	Repair Boundary Wall / Paint
367	Model Town Market Park.	55	1 Tubewell, 1 Fountain, 6 Games, 1	355'X205'	4	Through Agency	H.R International Tools Private Limited	Developed	Repair Boundary Wall / Paint
368	Model Town Oval Park Opp House No. 171 -L	55	11 Benches, 5 Games, 1 Hut	202'X122'	2	Through Matching Grant	Model Town Resident Welfare Society Oval Park	Under Developed	Repair Boundary Wall / Paint
369	426-R Model Town Near Eklavya School.	55	No Facilities	110'X56'X8'	1	Through School	Eklavya School	Under Developed	Repair Boundary Wall / Paint
370	Model Town Opp House No. 28-L Children Park	55	5 Games, 21 Benches, 2 Hut	632'X127'X14'	1	Through Matching Grant	Model Town Nature Care Society	Developed	Repair Boundary Wall / Paint
371	New Model Town Opp House No. 28	55	4 Benches	184'X44'	1	Through Matching Grant	Model Town Nature Care Society	Developed	Repair Boundary Wall / Paint
372	Model Town Telu Wali Park Opp House No. 130	55	11 Benches, 1 Hut, 1 Tubewell	135'X82'	1	Through Matching Grant	Guru Nanak Nagar Welfare Society	No Developed	Repair Boundary Wall / Paint
373	Parkash Nagar Opp House No. 85	55	2 Benches	111'X90'X35'	1	Through Matching Grant	Wefare Association Sunder Park Parkash Nagar	Developed	Repair Boundary Wall / Paint
374	Parkash Nagar Near Mata Rani Chowk Opp House No. 45	55	4 Games, 2 Benches, 1 Tubewell	105'X75'	1	Through Matching Grant	Parkash Nagar People Welfare Society	Developed	Repair Boundary Wall / Paint
375	Model Town Backside Gurudawara Sahib	55	39 Benches, 4 Hut, 9 Games, 1 Room, 1 Tennis Ground	500'X252'	2	Through Matching Grant	Model Town Welfare Society	Developed	Excellent
376	Model Town Kapoor Wali Park Opp House No. 87-R	55	1 Fountain, M.C. Quator 1 Community Hall, 1	475'X150'X70'	2	Through Matching Grant	Model Town West Welfare Society	Developed	Excellent
377	Model Town Rainbo Park Opp House No. 256-R	55	9 Games, 1 Fountain, 2 Hut, 16 Benches	385'X98'	2	Through Matching Grant	Rainbo Park Welfare Society	Developed	Good
378	Parkash Nagar Opp House No. 69/2	55	1 Tubewell, 1 Bathroom	125'X52'	Nil	M.C.J	M.C.J	No Developed	All Things Are Required Here.
379	Sat Kartar Nagar Near Johal Market Road	55	1 Tubewell, 3 Benches, 2 Games	100'X40'	1	Through Matching Grant	Samaj Sudhar Society Sat Kartar Nagar	Under Developed	Repair Boundary Wall / Paint
380	New Jawahar Nagar Near Chunmun Mall/House No. 221	56	1 Hut, 20 Benches, 3 Games	420'X15X165' (3-D	1	Through Matching Grant	New Jawahar Nagar Welfare Association	Developed	Repair Boundary Wall / Paint
381	New Colony Near International School Opp. Johal Market.	56	1 Tubewell, 5 Games, 8 Benches	324'X127'X7'	1	Through Matching Grant	New Colony Welfare Society	Developed	Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
382	Jyoti Nagar Near Opp. House No. 28	56	1 Tubewell, 1 Hut, 6 Games, 6 Benches	116'X56'	1	Through Agency	Sardar Singh Sidhu Memorial	Developed	Repair Boundary Wall / Paint
383	Jyoti Nagar Opp. House No. 80-A	56	1 Hut, 9 Benches, 2 Games	135'X60'	1	Through Agency	Sardar Singh Sidhu Memorial	Developed	1 Gate Broken Repair Boundary Wall / Paint
384	Urban State Phase 2 Opp Railway Line House No.. 990 Park No. 6	56	11 Benches	430'X67'X48"	1	Through Matching Grant	Go Green Citizen Welfare Form	Developed	Repair Boundary Wall / Paint/ No Lights
385	Urban State Phase 2 Opp Railway Line House No.. 243	56	Nil	190'X67'	1	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
386	New Jawahar Nagar Guru Amar Dass Park Opp Nanda Hospital House No. 26	56	1 Tubewell, 12 Benches, 4 Games	160'X127'	1	Through Matching Grant	Guru Amar Dass Welfare Society	Developed	Repair Boundary Wall / Paint/ Dry 3 Safeda Tree
387	Urban State Phase 2 Opp House No.. 378	56	11 Benches	110'X79'	1	M.C.J	M.C.J	Developed	No Light, No Footpath, Boundary Wall High Low
388	Urban State Phase 2 Opp House No.. 947	56	15 Benches, 4 Games	196'X188'	1	Through Matching Grant	Welfare Society Urban State Phase 2	Developed	Repair Boundary Wall / Paint/ Grill Is Broken
389	Urban State Phase 2 Opp House No.. 1199	56	2 Games, 10 Benches	142'X62'	1	Through Matching Grant	Welfare Society Urban State Phase 2	Developed	Repair Boundary Wall / Paint
390	Urban State Phase 2 Opp House No.. 1488 D Block	56	1 Tubewell, 6 Benches	100'X72'	1	Through Matching Grant	Shri Gobind Park Welfare Society Phase 2	Developed	Repair Boundary Wall / Paint
391	Urban State Phase 2 Opp House No.. 993 Park No. 10	56	7 Benches, 2 Hut, 2 Games	114'X88'	1	Through Matching Grant	Go Green Citizen Welfare Form	Developed	Excellent
392	Urban State Phase 2 Opp House No.. 467 Park No.12	56	8 Benches	117'X74'	1	M.C.J	M.C.J	Under Developed	Repair Light, Gate, Paint, Boundary Wall
393	Ranjit Enclave Opp House No.. 90	56	8 Benches	70'X50'	1	Through Matching Grant	Sudhar Sabha Committee Vill Lohar Nagal	Developed	Repair Boundary Wall / Paint
394	Ranjit Enclave Back Side Councillor Resident	56	8 Benches, 5 Games	89'X50'	1	Through Matching Grant	Sudhar Sabha Committee Vill Lohar Nagal	Under Developed	Repair Boundary Wall / Paint
395	New Kalgeedarh Avenue Lane No. 1	56	4 Benches	119'X64'	1	Through Matching Grant	Sudhar Sabha Committee Vill Lohar Nagal	Under Developed	No Footpaht & Light, No Water Supply, Repair Boundary Wall / Paint/ No Games
396	Punjabi Bagh Extension Opp House No. 24	56	Benches, 1 Tubewell	144'X135'X36'	1	Through Matching Grant	Punjabi Bagh Extension Welfare Society	Under Developed	Repair Boundary Wall / Paint
397	Urban State Phase 2 Opp House No.. 2007 Park No.9 Near Ganda Nala	56	7 Benches	178'X110'X64'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
398	Ishwarpuri House No.. Opp House No. 43	56	1 Hut, 3 Games	131'X89'	2	Through Matching Grant	Sudhar Sabha Committee Vill Lohar Nagal	Under Developed	Repair Boundary Wall / Paint
399	Ranjit Avenue Opp House No..54/55 Shamshan Ghat Kabjie Wali Park	56	1 Hut	120'X88'	Nil	M.C.J	M.C.J	No Developed	Gate Locked
400	Urban State Phase 2 Opp House No.. 239 Back Side Gurudawara Sahib	56	1 Tubewell, 4 Games, 18 Benches	164'X109'	1	Through Matching Grant	Apna Park Welfare Society Urban State Phase 2	Developed	Repair Boundary Wall / Paint
401	Urban State Phase 2 Opp House No.. 355	56	1 Water Tank, 32 Benches, 1 Fountain, 4 Games	200'X189'	1	Through Matching Grant	Welfare Society Park 2 Urban State Phase 2	Under Developed	Repair Boundary Wall / Paint
402	Urban State Phase 2 Opp House No.. 646	56	No Facilities	112'X91'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint
403	Urban State Phase 2 Opp House No.. 1522	56	7 Benches, 1 Games	111'X91'	1	Through Matching Grant	Welfare Society Park 2 Urban State Phase 2	Developed	Repair Boundary Wall / Paint
404	Urban State Phase 2 Opp House No.. 88	56	8 Benches, 6 Games	181'X107'	1	Through Matching Grant	Resident Welfare Form Urban State Phase2	Developed	Repair Boundary Wall / Paint
405	Urban State Phase 2 Opp House No.. 283 Backside Little Blose School.	56	22 Benches, 6 Games	181'X127'	1	Through Matching Grant	Resident Welfare Form Urban State Phase2	Developed	Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardener	Status Of The Gardener (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
406	Urban State Phase 2 Opp House No.. 344 Park No.5 A	56	4 Benches	98'X91'	1	Through Matching Grant	Resident Welfare Form Urban State Phase2	Developed	Repair Boundary Wall / Paint
407	Urban State Phase 2 Opp House No.. 345	56	No Facilities	154'X205'	1	Through Matching Grant	Resident Welfare Form Urban State Phase2	Developed	Repair Boundary Wall / Paint
408	Urban State Phase 2 Opp P.P.R Mall	56	1 Tubewell	100'X70'X15'	Nil	M.C.J	M.C.J	No Developed	Grill Are Broken/ Repair Boundary Wall / Paint
409	Mithapur Near Gurudawara Shahib 3- D Park	57	12 Benches, 1 Hut	297'X260'X184'	1	M.C.J	M.C.J	Developed	Excellent
410	Indra Park Opp House No. 9	57	4 Games	190'X61'	1	Through Matching Grant	Indra Park Welfare Society	Developed	Games Are Broken/ Repair Boundary Wall / Paint
411	Doordarshan Enclave Phase 2 Opp House No. 118	57	No Facilities	95'X50'	Nil	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint/ No Footpath/ Gate & Grill Broken
412	Bank Colony Opp House No. 26	57	6 Benches	78'X58'	1	Through Matching Grant	Bank Colony Welfare Association	Under Developed	Repair Boundary Wall / Paint/ No Grass In The Park
413	Prince Plaza Opp House No. 2	57	8 Benches, 3 Games	70'X70'	1	Through Matching Grant	Prince Plaza Welfare Society Mithapur Road	Developed	No Grill, Only Boundary Wall, No Light
414	Makhan Shah Lubhana Nagar Mithapur Opp House No. 37 To 24	57	No Facilities	75'X50'	1	Through Matching Grant	The Welfare Society Mithapur	Under Developed	Only Boundary Wall Without Grill, No Light
415	Ravinder Nagar Opp House 59-B	57	6 Benches, 1 Tubewell	135'X55'	1	Through Matching Grant	Ravinder Nagar Welfare Society	Developed	Boundary Wall & Grill Height Is Low
416	Dada Nagar Opp House No. 33	57	9 Benches, 4 Games	105'X45'	1	Through Matching Grant	Dada Nagar Welfare Society	Developed	Repair Boundary Wall / Paint
417	Green Avenue Opp House No. 11/20	57	15 Benches, 3 Games	155'X80'	1	Through Matching Grant	Green Avenue Welfare Society	Developed	Repair Boundary Wall / Paint
418	Cheema Nagar Opp House No. 140	57	4 Benches, 2 Games, 1 Dispensary	127'X52'	1	Through Matching Grant	Shaheed Captain H.P.S Dhami Nagar Welfare Society	Under Developed	Repair Boundary Wall / Paint
419	Bank Enclave Opp House No. H.C.F -16	57	6 Benches, 2 Games, 1 Tubewell	75'X70'	1	Through Matching Grant	Bank Enclave Welfare Association	Developed	Repair Boundary Wall / Paint
420	Green Model Town Near Innocent Heart School	57	1 Hut, 8 Benches	105'X75'	1	Through Matching Grant	Green Model Town Welfare Society	Under Developed	No Light/Repair Boundary Wall / Paint
421	Kewal Vihar Opp House No. 59 Army Colony	57	9 Games, 9 Benches	280'X75'	1	Through Matching Grant	The Kewal Vihar Housing Maintenance	Developed	No Boundary Wall
422	Kewal Vihar Opp House No. 21	57	No Facilities	96'X63'	Nil	M.C.J	M.C.J	Under Developed	No Boundary Wall
423	Kewal Vihar Opp House No. 32	57	1 Tubewell	100'X75'X10'	Nil	M.C.J	M.C.J	Under Developed	No Boundary Wall
424	Green Model Town Near Sabji Mandi	57	1 Bench	63'X55'	Nil	M.C.J	M.C.J	No Developed	Repair Boundary Wall / Paint/ No Grass & Plants
425	Khurla Kingra Shamshan Ghat	57	8 Benches, 1 Tubewell	280'X150'	2	Through Matching Grant	Nagar & Shamshan Ghat Sudhar Committee	No Developed	Repair Boundary Wall / Paint
426	Kot Sadiq Shamshan Ghat Park	58	No Facilities	75'X35'	1	Through Matching Grant	New Model House Development Society	Under Developed	No Facilities
427	Jallow Wali Abadi Shamshan Ghat Park	58	No Facilities	295'X120'X100'	2	Through Matching Grant	New Model House Development Society	Developed	No Benches, No Games
428	Geeta Colony Opp House No. 17	58	1 Hut	150'X75'	2	Through Matching Grant	New Model Park House Development	Under Developed	Repair Boundary Wall / Paint/ Gate Is Broken
429	Kot Sadiq Opp Govt. Primary School	58	1 Tubewell, 1 Sewa Kendar	200'X120'X45'	2	Through Matching Grant	New Model House Development Society	Under Developed	No Light, No Water Supply, Repair Boundary Wall / Paint

Sr. No	Name & Location Of The Park	Ward No.	Facilities In The Park	Measurement	No. Of The Gardner	Status Of The Gardner (Regular Or Contractual)	Name Of The Caretaker Weather Maintained By Society, Ngo Or Mcj	Status Developed/Under Developed/Not Developed	Remarks
430	Deol Nagar Opp House No. 49/7	59	10 Benches, 1 Tubewell	150'X65'	-	Maintained By	Mohalla	Developed	Required Gates
431	Professor Colony Tubewell Wali Park	60	1 Tubewell	200'X100'	2	Through Matching Grant	Park Avenue Welfare Society	Under Developed	No Boundary Wall, No Games
432	Park Avenue Opp House No. 14-15	60	1 Tubewell, 1 Game	120'X87'	1	Through Matching Grant	Park Avenue Welfare Society	Developed	No Footpath/ No Light/Repair Boundary Wall / Paint
433	Bomby Nagar Opp House No. 279	60	6 Benches, 1 Tubewell	152'X100'	2	Through Matching Grant	Park Avenue Welfare Society	Under Developed	No Footpath/ No Light/Repair Boundary Wall / Paint
434	Guru Teg Bahadur Nagar Opp House No. 306	60	2 Benches	163'X196'1'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint
435	Guru Teg Bahadur Nagar Opp House No. 488	60	6 Benches	92'X60'	1	Through Matching Grant	Guru Teg Bahadur Vikas Shabha	Developed	Repair Boundary Wall / Paint
436	Guru Teg Bahadur Nagar Chotti Park Opp House No. 556	60	2 Games, 1 Tubewell	67'X37'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
437	Guru Teg Bahadur Nagar Opp House No. 554	60	No Facilities	112'X71'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
438	Guru Teg Bahadur Nagar Opp House No. 231 Mata Gujri Ji Park	60	33 Benches, 12 Games, 2 Hut	223'X188'	2	Through Matching Grant	Guru Teg Bahadur Resident Welfare Association	Developed	Excellent
439	Guru Teg Bahadur Nagar Opp House No. 149	60	2 Hut, 1 Fountain, 12 Games, 23 Benches	180'X60'	2	Through Matching Grant	Bhai Mati Dass Park Welfare Society	Developed	Repair Boundary Wall / Paint
440	Guru Teg Bahadur Nagar Opp House No. 347 Tanki Wali Park	60	1 Fountain, 8 Games, 18 Benches, 1 Hut	314'X171'	3	Through Matching Grant	Bhai Dayala Ji Welfare Society	Developed	Repair Boundary Wall / Paint
441	Housing Board Colony Opp House No. 810/9	60	7 Games, 7 Benches, 1 Hut	176'X82'	1	Through Matching Grant	Guru Kirpa Mehala Welfare Society	Developed	Repair Boundary Wall / Paint
442	Housing Board Colony Opp House No. 811/1	60	1 Tubewell	95'X50'	1	M.C.J	M.C.J	Under Developed	Repair Boundary Wall / Paint
443	Housing Board Colony Opp House No. 798/1	60	4 Benches, 1 Game	146'X48'10'	1	Through Matching Grant	Housing Board Welfare Association	Developed	Repair Boundary Wall / Paint
444	F.C.I Colony Opp House No.41	60	1 Hut, 3 Games, 8 Benches	174'X210'X78'	1	Through Matching Grant	F.C.I Colony Welfare Society	Developed	Repair Footpath, Lights
445	F.C.I Colony Opp House No.62	60	8 Benches, 3 Games, 1 Tubewell	108'X60'122'	1	Through Matching Grant	F.C.I Colony Welfare Society	Developed	Repair Boundary Wall / Paint
446	Housing Board Colony Opp House No. 832 Near Model Town Shamshan Ghat	60	4 Benches, 2 Games	105'X50'X20'	1	M.C.J	M.C.J	Developed	Repair Boundary Wall / Paint